

## CONTENTS

- 1 Introduction [T.W. deLoos, R.D. Weir]
- 2 Phase Changes in Pure Component Systems: Liquids and Gases [S. Verevkin]
  - 2.1 Static Measurements
  - 2.2 Ebulliometry
  - 2.3 Knudsen Effusion Methods for Vapour Pressure Measurement
    - 2.3.1 Conventional Mass Loss Technique
    - 2.3.2 Torsion-Effusion Method
    - 2.3.3 Simultaneous Torsion and Mass-Loss Effusion Technique
    - 2.3.4 Isothermal Knudsen Effusion Method in (TG)-type Apparatus
    - 2.3.5 Non-Isothermal Knudsen Effusion Method in (TG)-type Apparatus
    - 2.3.6 Mass Loss Knudsen Technique with a Quartz Crystal Microbalance
    - 2.3.7 Mass Loss Knudsen Technique by Heat-Conducting Calorimetry
    - 2.3.8 Mass Loss Knudsen Technique by a Mass Spectrometry Method
    - 2.3.9 Knudsen Cell by Differential Scanning Calorimetry (DSC)
      - 2.3.9.1 DSC as a Boiling Point Method
      - 2.3.9.2 DSC as a Mass Loss Method
  - 2.4 Langmuir Effusion Methods for Vapour Pressure Measurement
  - 2.5 The Transpiration Method
  - 2.6 Chromatographic Methods
    - 2.6.1 Head Space Analysis
    - 2.6.2 GC-Correlations with Retention times and Vapour Pressures of Reference Compounds
    - 2.6.3 GC-Correlations with Net Retention Times
  - 2.7 Calorimetric Measurements of the Enthalpy of Vaporization
    - 2.7.1 Adiabatic Calorimeters
    - 2.7.2 Drop Calorimetry
    - 2.7.3 Differential Calorimetry
  - 2.8 Conclusions
- 3 Phase Changes in Pure Component Systems: Liquids and Solids [A. Würflinger]
  - 3.1 Thermal Methods and Calorimetry
    - 3.1.1 Measurements at Normal Pressure
      - 3.1.1.1 Adiabatic Calorimetry
      - 3.1.1.2 Ice Calorimetry
      - 3.1.1.3 Dynamic Methods
      - 3.1.1.4 Levitation Techniques
      - 3.1.1.5 Time-Temperature Methods
    - 3.1.2 Measurements at High Pressure
      - 3.1.2.1 Calorimetry

- 3.1.2.2 DTA and DSC
    - 3.1.2.3 Thermobarometry
    - 3.1.2.4 Piezothermal Method
    - 3.1.2.5 Thermal Conductivity Measurements
  - 3.2 Density and Volume Changes
    - 3.2.1 Measurements at Normal Pressure
    - 3.2.2 Measurements at High Pressure
  - 3.3 Melting Curves at High Temperatures and Pressures
  - 3.4 Miscellaneous Methods
    - 3.4.1 Dielectric Measurements
    - 3.4.2 Ultrasonic Measurements
    - 3.4.3 Other Methods
  
- 4 Phase Changes in Pure Component Systems: Solid and Solid [R.D. Weir, K.A. Sosin]
  - 4.1 Classification of Solid-Solid Phase Transitions
  - 4.2 Thermodynamics of Solid-Solid Phase Transitions
  - 4.3 Introduction into Soft Modes and the Central Peak
  - 4.4 Phase Transitions in Plastic Crystals and Fullerenes
  - 4.5 Experimental Techniques
    - 4.5.1 Thermal Methods
    - 4.5.2 Optical Methods
    - 4.5.3 X-ray and Neutron Scattering
      - 4.5.3.1 Elastic Scattering (diffraction)
      - 4.5.3.2 Inelastic Scattering
    - 4.5.3 Ultrasonics
    - 4.5.5 Magnetic Resonance
  - 4.6 Recent Developments
    - 4.6.1 Inorganic Compounds
    - 4.6.2 Organic Compounds
    - 4.6.3 Fullerenes
    - 4.6.4 Advances in Experimental Techniques and Interpretation of Results
  
- 5 Vapour-Liquid Equilibrium at Low Pressure [J.D. Raal, D. Ramjugernath]
  - 5.1 Equipment and Procedures
    - 5.1.1 Static Methods
    - 5.1.2 Computations from Static Cell Data
    - 5.1.3 Semi-micro Cells
    - 5.1.4 Data Reduction from P-x Measurements
    - 5.1.5 Sensitivity of Temperature and Pressure

## 5.2 Dynamic Methods

- 5.2.1 Attainment of Equilibrium
- 5.2.2 Partial Condensation of Equilibrium Vapour
- 5.2.3 Smooth Boiling
- 5.2.4 Measurement and Control of Temperature and Pressure
- 5.2.5 Measurement of Composition

## 5.3 Conclusions

# 6 Vapour-Liquid Equilibrium at High Pressure [D. Richon, T.W. deLoos]

## 6.1 Closed Circuit Methods

- 6.1.1 Static-analytic Methods
  - 6.1.1.1 Sampling
  - 6.1.1.2 *In-situ* Analyses
- 6.1.2 Quasi-static Methods
  - 6.1.2.1 Mechanical Circulation
  - 6.1.2.2 Thermal Circulation
- 6.1.3 Static-synthetic Methods
  - 6.1.3.1 Direct Determination of Bubble or Dew Points
  - 6.1.3.2 Simultaneous Determination of Bubble and Dew Point Properties
  - 6.1.3.3 Measurements of Total Pressure

## 6.2 Open Circuit Methods

- 6.2.1 Forced Circulation of the Mixture
  - 6.2.1.1 Sampling
  - 6.2.1.2 *In situ* Analyses
- 6.2.2 Open Flow of the Gas Phase
  - 6.2.2.1 Stripping Method
  - 6.2.2.2 Retention Time Methods

## 6.3 Conclusions

# 7 Low Pressure Gas Solubility in Liquids [E. Wilhelm]

## 7.1 Thermodynamics

- 7.1.1 Fundamentals
- 7.1.2 Practical Implementation
  - 7.1.2.1 The Vapour Phase
  - 7.1.2.2 The Liquid Phase

## 7.2 Instrument, Experimental Techniques, Data Correlation and Selected Results

## 7.3 Conclusions

# 8 Liquid-Liquid Equilibrium [J. Matouš, K. Řehák, J.P. Novák]

- 8.1 Liquid-Liquid Equilibrium in Binary Systems
  - 8.1.1 Direct Analytical Methods
  - 8.1.2 Synthetic or Turbidimetry Method
    - 8.1.2.1 Cloud-point Method
    - 8.1.2.2 Titration Method
  - 8.1.3 Volumetric Method
  - 8.1.4 Indirect Methods
  - 8.1.5 Measurements of Very Low Mutual Solubility
    - 8.1.5.1 Dynamic Flow Method
    - 8.1.5.2 Circulation Apparatus for Solute Vapour Saturation
  - 8.1.6 Measurements in the Vicinity of the Critical Point
  - 8.1.7 Testing System

- 8.2 Liquid-Liquid Equilibrium in Ternary and Multi-Component Systems
  - 8.2.1 Determination of the Equilibrium Curves in Ternary or Pseudo-ternary Systems
  - 8.2.2 Direct Analytical Method
  - 8.2.3 Determination of Tie-lines in Ternary Systems using Binodal Curves
  - 8.2.4 Determination of the Distribution or Partition Coefficient
    - 8.2.4.1 Shake-flask Method
    - 8.2.4.2 Slow-stirring Method
    - 8.2.4.3 Generator-column Method
    - 8.2.4.4 Counter-current Chromatography
    - 8.2.4.5 Reversed Phase High Pressure Liquid Chromatography
    - 8.2.4.6 Distribution Coefficient and the Experimental Limiting Activity Coefficients

### 8.3 Basic Monographs

## 9 Condensed Phases of Organic Materials: Solid-Liquid and Solid-Solid Equilibrium

[H.A.J. Oonk, J.K.L. Tamarit]

### 9.1 Thermodynamic Treatment

### 9.2 Experimental

- 9.2.1 Sample Preparation
- 9.2.2 Microcalorimetry
- 9.2.3 X-ray Diffraction
- 9.2.4 Higher Order Phase Transitions

### 9.3 Key Systems

- 9.3.1 Naphthalene + 2-Naphthol
- 9.3.2 Tricosane + Pentacosane
- 9.3.3 2,2-dimethylpropane + Carbon Tetrachloride

### 9.4 Empirical Relationships

### 9.5 Concluding Remarks

10 Condensed Phases of Inorganic Materials: Metallic Systems [K.M. Jaansalu, M.H. Kaye, W.T. Thompson]

10.1 Solution Thermodynamics and Phase Diagram Development

10.2 Experimental Methods

10.2.1 Microscopic Phase Examination

10.2.2 X-ray Diffraction

10.2.3 Emf Cells

10.2.4 Vapour Pressure Techniques

10.2.5 Thermal Methods

10.2.6 Scanning Calorimetry

10.2.7 Calorimetric Methods

10.3 Multi-component Systems

10.4 Conclusion

11 Condensed Phases of Inorganic Materials: Ceramic Systems [N.S. Jacobson, R.L. Putnam, A. Navrotsky]

11.1 Techniques Yielding Enthalpy of Formation

11.1.1 Combustion Calorimetry

11.1.2 Solution Calorimetry

11.2 Techniques Yielding Heat Capacity and Enthalpy

11.2.1 Drop Calorimetry

11.2.2 Differential Thermal Methods

11.2.3 Adiabatic Calorimetry

11.3 Techniques Yielding Partial Molar Quantities

11.3.1 Gas Equilibration Techniques

11.3.2 Knudsen Cell Methods

11.3.3 Electrochemical Techniques

11.4 Conclusion

12 Condensed Phases of Inorganic Materials: Molten Salts

12.1 Structure of Molten Salts

12.2 Experimental Determination of Thermodynamic Properties

12.2.1 Calorimetric Measurements

12.2.2 Vapour Pressure Methods

12.2.3 Electrochemical Methods

12.2.4 Solubility Measurements

12.2.5 Cryoscopy

12.3 Thermodynamic Properties from Phase Diagrams

12.4 Solid and Gas Phases

12.4.1 Differential Thermal Analysis

12.4.2 Mass Spectroscopy

12.5 Conclusion

### 13 Measurement of Limiting Activity Coefficients Using Non-Analytical Tools

[J.D. Raal, D. Ramjugernath]

- 13.1 Experimental Methods
- 13.2 Differential Ebulliometry and Equipment
- 13.3 Characterisation of an Ebulliometer
  - 13.3.1 Principal Ebulliometer Equation
  - 13.3.2 Evaluation of the E Parameter
  - 13.3.3 Evaluation of Holdups ( $R'/S'$ ) and ( $V'/S'$ )
  - 13.3.4 Determination of Vaporization Ratio  $\phi$ 
    - 13.3.4.1 Iterative Procedure
    - 13.3.4.2 Procedure Based Microscopic Energy Balance
- 13.4 Static Differential Methods
  - 13.4.1 Calculation of Equilibrium Liquid Composition  $x_1$
  - 13.4.2 Calculation of Activity Coefficient at Infinite Dilution  $\gamma_i^\infty$
- 13.5 Inert Gas Stripping
  - 13.5.1 Attainment of Equilibrium
  - 13.5.2 Calculation of Activity Coefficient at Infinite Dilution  $\gamma_i^\infty$
- 13.6 Conclusion

### 14 Measurement of Limiting Activity Coefficients Using Analytical Tools [V. Dohnal]

- 14.1 Retention Measurements in Gas-Liquid Chromatography (GLC)
  - 14.1.1 Conventional GLC
  - 14.1.2 Relative GLC
  - 14.1.3 Non-Steady State GLC
- 14.2 Headspace Method of Analysis
- 14.3 Methods of the Static Mass Balance
  - 14.3.1 Equilibrium Partitioning in Closed Systems
  - 14.3.2 Phase Ratio Variation
  - 14.3.3 Headspace Stepwise Extraction
- 14.4 Rate Measurements on Continuous Gas-Liquid Separation Processes
  - 14.4.1 Inert Gas Stripping
  - 14.4.2 Method of Exponential Saturator
- 14.5 Methods of Distillation
  - 14.5.1 Rayleigh Distillation
  - 14.5.2 Differential Distillation
  - 14.5.3 Measurements by Circulation Stills
- 14.6 Concluding Remarks

- 15 Measurement of Interfacial Tension [M.J.B. Evans]
- 15.1 Terminology
  - 15.2 Static Methods
    - 15.2.1 Capillary Rise and Related Methods
    - 15.2.2 Drop and Bubble Shape Methods
    - 15.2.3 Spinning Drop Method
    - 15.2.4 Oscillating Drop Method
  - 15.3 Quasi or Detachment Methods
    - 15.3.1 Volume or Weight Method
    - 15.3.2 Du Noüy Ring
    - 15.3.3 Wilhelmy Plate
    - 15.3.4 Maximum Bubble Pressure Method
  - 15.4 Dynamic Surface and Interfacial Tension
    - 15.4.1 Oscillating Jet Method
    - 15.4.2 Capillary Wave Methods
    - 15.4.3 Oscillating Drop and Bubble Methods
    - 15.4.4 Maximum Bubble Pressure Method
    - 15.4.5 Capillary Pressure and Related Methods
- 16 Critical Parameters [A.S. Teja, J. Mendez-Santiago]
- 16.1 Experimental Techniques
    - 16.1.1 Sealed Ampoule Method
    - 16.1.2 Flow Method
    - 16.1.3 Spontaneous Boiling Methods
    - 16.1.4 Open Tube Methods
    - 16.1.5 Methods Based on the PVT Behaviour of a Substance
    - 16.1.6 Other Methods
  - 16.2 Note on Experimental Errors
  - 16.3 Extrapolation Techniques