

## LEGENDS TO FIGURES

Fig 1. A photograph of a Finn Knee prosthesis.

Fig 2. Radiographs of the prosthesis five years after replacement of the proximal tibia.

A: Anteroposterior view, B: Lateral view, C: Press-fitted tibial component

Excellent bone ingrowth was observed without evidence of loosening.

Fig 3. Radiograph of a tibial yoke breakage that occurred 10 months after implantation.

Fig 4. Radiograph of a distal femoral replacement three years after implantation.

Fig 5. Kaplan-Meier curve of the prosthetic survival in the 32 patients.

Fig 6. Kaplan-Meier curves of the prosthetic survivals according to the location of the tumor.

Patients who had a proximal tibial replacement had significantly worse prosthetic survivals than those with a distal femoral replacement (univariate,  $p = 0.04$ ; multivariate,  $p = 0.05$ ).